




2/24: Replaced consumable components on the anion analyzer, analyzed QC samples – 3/4: Replaced all sample delivery system filters, anion analyzer issue, stopped analyzer – 3/9: Replaced sonde, decommissioned Turner CE fluorometer – 3/22: Replaced all sample delivery system filters, analyzed QC samples – 4/8: Replaced all sample delivery system filters, replaced sonde, performed maintenance on carbon analyzer



2/24: Replaced all sample delivery system filters, analyzed QC samples – 3/4: Replaced 100 um sample delivery system filter, replaced consumable components on the anion analyzer – 3/10: Anion analyzer manufacturer technician at site to fix software issue – 3/22: Replaced all sample delivery system filters, analyzed QC samples – 4/4: Cycled power on anion analyzer prep module to get it to run, cleaned anion sample lines, cleaned carbon analyzer lines, cleaned sonde, replaced 100 um sample delivery system filter – 4/15: Replaced sonde, replaced all sample delivery system filters – 4/20: Replaced sonde, replaced 100 um sample delivery system filter, analyzed QC samples, issue with how the check standard runs, will troubleshoot



2/25: Analyzed QC samples, cleaned sonde housing – 3/11: Replaced sonde, cleaned carbon and analyzer lines, replaced carbon analyzer consumable – 3/24: Analyzed QC samples, replaced sample delivery system filters, cleaned filter housings, carbon analyzer would not run grab samples, will troubleshoot next time at the station – 3/28: Stopped anion analyzer due to a component leak, need new part to fix the leak, contacted the carbon analyzer manufacturers technical support to troubleshoot the grab sample issue from last time, will continue to work with them to resolve the problem – 4/5: Installed new part on anion analyzer to fix the leak issue, fixed, carbon analyzer still has grab sample analysis issues, will continue to troubleshoot – 4/13: Replaced sonde, cleaned anion analyzer lines, checked carbon analyzer flow rate during analysis and backflushed lines per manufacturers technician directions, grab sample flow still not flowing – 4/21: Analyzed anion QC samples, still working on a fix for grab sample analysis on the carbon analyzer




2/22: CDEC reporting issue – 2/24: Replaced all sample delivery system filters, analyzed QC samples – 3/10: Replaced the 1 um filter – 3/17: Anion analyzer stopped operation, reconnected the sample prep module and restarted the analyzer – 3/23: Replaced all sample delivery system filters, replaced consumable component on carbon analyzer, removed hyacinth that accumulated under the station – 3/25: The carbon analyzer stopped reporting, restarted data software which fixed the glitch, removed more hyacinth – 4/5: Removed more hyacinth, primrose and duckweed which made up a flotilla under the station










2/25: Replaced all sample delivery system filters, analyzed all QC samples – 3/3: Carbon data software closed, restarted the software – 3/9: Carbon data software stopped again, restarted, possible power outage – 3/10: Replaced the 1 um sample delivery system filter – 3/28: Replaced all sample delivery system filters, replaced consumable components on the carbon analyzer – 4/21: Replaced all sample delivery system filters, analyzed QC samples



Bromide &amp; EC Summary



Delta Pumping



— HRO — TRP — GPP Pumping — GPP Generation — OGP Pumping — OGP Generation — DSA — SBA — BKS



Precipitation &amp; Flow

