




6/21: Sonde water not flowing due to mud in line – 7/6: Changed all system filters and sonde – 7/19: Changed the 100 um filter, Analyzed all QC samples – 7/28: Computer went down, restarted it and all associated programs – 8/1: Had to restart the computer again, cleaned sonde flow through cell – 8/9: Changed all system filters, cleaned sonde – 8/10: Exchanged sonde – 8/16: Wireless antenna was down due to wind, it was put back in place – 8/18: Changed the 1 um filter




6/23: Analyzed all QC samples, changed filters and cleaned housings, sonde still not sending data – 7/6: Changed sonde and the 100 and 50 um filters – 7/25: Analyzed QC samples, changed all system filters and cleaned housings, changed the cable from the sonde to the adapter but is still not reporting – 8/10: Exchanged sonde, changed 100 um filter – 8/17: Analyzed QC samples, sonde still not reporting




6/21: Changed all system filters except 0.45 um, rinsed sonde, restarted computer and programs due to a power outage – 7/1: Restarted the carbon analyzer due to an apparent power outage, changed all system filters, rinsed sonde and housing – 7/6: Exchanged sonde – 7/19: Changed all system filters except 0.45 um, anion analyzer underwent a calibration, sonde reporting % Sat instead of mg/L for DO, set new template to correct this, did not work, will troubleshoot – 7/22: Cleaned carbon analyzer lines, synced the analyzer clock with the computer clock – 7/26: Carbon analyzer component issue, the degasser was bypassed temporarily until a new degasser is obtained – 7/28: Installed new component on the carbon analyzer (ICR), values appear normal, changed all system filters, rinse sonde – 8/9: Replaced the 100 un filter, rinsed sonde – 8/10: Exchanged sondes – 8/18: Replaced anion analyzer components and recalibrated, analyzed QC samples, changed all system filters










6/22: Analyzed QC samples, changed all filters - 6/27: Retention time shift needed for Bromide, then done for other anions. 7/14: Anion communication issue, reconnected through remote desktop. 7/22: Analyzed QC samples, changed all filters. DOC stream had stopped on 7/18 due to relay burnout on datalogger controlling the solenoid valve. The wiring was moved to a new relay. 8/8: Anion communication issue, reconnected through remote desktop - 8/9: Anion communication issue, reconnected through remote desktop - 8/15: Anion communication issue, reconnected through remote desktop - 8/18: Analyzed QC samples, changed all filters. Added new hazmat collection containers for the analyzer waste streams.









Delta Pumping



— HRO — TRP — GPP Pumping — GPP Generation — OGP Pumping — OGP Generation — DSA — SBA — BKS

Precipitation & Flow



- CSU Sacramento    Redding Fire Station    Friant Dam    Sac R at Freeport    Sac R at Vina-Woodson Br    Tuolumne R at Modesto    Stanislaus R at Ripon    SJR R at Vernalis
- Oroville Dam    Exchequer Dam, Merced R.    Stockton Fire Station    Sac R at Verona    SJR at Crows Landing